

Client Name:

Brine Service Company

Site Location:

1622 Goldston Rd, Corpus Christi, Nueces County, Texas

Project No. 30404056

Photo No.

Date: 10/19/10

Description:

View looking north from Lot 5. Grassy area is Lot 4. Goodyear and Wingfoot signs are on Lot 3.



Photo No.

Date: 11/3/16

Description:

View looking north at southeast corner of Wingfoot Tire Store





Client Name:

Site Location:

Project No.

Brine Service Company

1622 Goldston Rd, Corpus Christi, Nueces County, Texas

30404056

Photo No.

Date: 11/3/16

Description:

View looking west at rear (east side) of Wingfoot Tire Store



Photo No.

Date:

Description:

View looking west at north side of Wingfoot Tire Store





Client Name:

Site Location:

Project No.

Brine Service Company

1622 Goldston Rd, Corpus Christi, Nueces County, Texas

30404056

Photo No. **5**

Date:

Description:

View looking north at south side of Wingfoot Tire Store building



Photo No.

Date: 11/9/10

Description:

Looking south at bay doors for Wingfoot Tire Store building during installation of ENSB06/TWGW12





Client Name:

Brine Service Company

Site Location:

1622 Goldston Rd, Corpus Christi, Nueces County, Texas

Project No.

30404056

Photo No.

Date: 1/18/18

Description:

Closeup of lead weights embedded in asphalt on north side of Wingfoot Tire Store. Compared to small glove.



Photo No.

Date: 1/18/18

Description:

Closeup of lead weights embedded in asphalt on north side of Wingfoot Tire Store. Compared to small glove.





Client Name:

Brine Service Company

Site Location:

1622 Goldston Rd, Corpus Christi, Nueces County, Texas

Project No.

30404056

Photo No.

Date: 1/18/18

Description:

Lead weights on asphalt drive on north side of Wingfoot Tire store (inside red circles)



Photo No.

Date: 10/18/16

Description:

Lead weights picked up from asphalt drive at Wingfoot Tire store

